

## **PORTMOAK CC ROAD REPORT SUMMARY**

Description	Details	Notes	With	First Reported	Revised
A911 Scotlandwell to Bowhouse	Following recent accidents the decision not to retain the national speed limit on this stretch of road should be reconsidered	In light of the recent report of the Enforcement Officer that the required visibility splay conditioned in the original planning consent was unachievable, the matter would be taken forward with the PKC Roads Department (WCllr Giacomazzi).	<b>PKC</b>	08 April 2014	19 January 2015
Dryside Road from Wester Balgedie to the Fife boundary	Recent road improvement works on the Fife section of Dryside road has resulted in a considerable increase in HGV traffic resulting in damage to the road edges.	PKC will consider this for "Green Route" status. If agreed this should provide protection to cyclists and walkers (WCllr Robertson).	<b>PKC</b>	12 May 2014	19 January 2015
A911 Wellside, south exit	The section of road from Wellside Motors to the build out as you exit South is breaking up along the centreline of the road and on the left-hand verge	Potholes to be repaired and the proposed mini-roundabout should not now be installed in the light of the construction of a build-out since the mini roundabout was required in the planning permission (WCllr Robertson).	<b>PKC</b>	13 May 2014	19 January 2015
Reflective strips at build outs	It has been reported that the reflective strips on many of the build outs are showing signs of aging & reduced reflectiveness	Maintenance to be carried out shortly. Uncertainty remains on whether reflective kerb strips are to be installed to improve build-out visibility as the CC believes they should be (WCllr Robertson).	<b>PKC</b>	10 December 2013	19 January 2015
Grit Bins, additional	Request made for 2 additional grit bins.	Decision remains unclear	<b>PKC</b>	10 December 2013	19 January 2015
Speed limit Portmoak Primary	A request has been made for a full time mandatory 20mph speed limit in the roads surrounding Portmoak Primary School.	Pilot project in preparation	<b>PKC</b>	10 December 2013	19 January 2015
Repair to traffic island at the east end of the B9097 Ballingry junction (South Loch Road.)	Road markings badly faded making it difficult to distinguish RH slip road, curbed traffic island poorly identified.	This will happen shortly, weather permitting (WCllr Robertson).	<b>PKC</b>	23 October 2013	19 January 2015
Cats Eyes	Many of existing cats eyes "blind"	Agreed by PKC to be done but no date as yet for installation.	<b>PKC</b>	09 April 2013	19 January 2015
Improved signage Wester Balgedie A911 junction	Improvement required to the signage, road markings & additional anti-skid surfacing at the junction with the A911 from Wester Balgedie, particularly relating to the sharpness of the corner & the blind summit	Signage for cyclists and pedestrians request for signage made (WCllr Robertson). Improved antiskid surface under consideration	<b>PKC</b>	09 April 2013	19 January 2015

## **PORTMOAK CC ROAD REPORT SUMMARY**

Description	Details	Notes	With	First Reported	Revised
Resurfacing B9097 South Loch Road	The surface on the B9097 was partially resurfaced in the financial year 2013/14.	No known timescale.	<b>PKC</b>	09 April 2013	08 December 2014
Footpath from Pormoak church to Scotlandwell	The section of public footpath next to the road leading from Portmoak Church to Wester Balgedie is the last remaining section of the footpath network that connects the Portmoak villages. It is still of an outdated design making it difficult to use safely.	PKC considering options	<b>PKC</b>	08 December 2014	19 January 2015
Snow clearing Winter 2014/15	PKC bad weather arrangements	Difficulties in finding a suitable contract for local volunteers have not been resolved	<b>PKC</b>	09 April 2013	19 January 2015
New footpath at Easter Balgedie	Consideration to be given to the road safety arrangement where the new Wester Balgedie to Easter Balgedie path terminates at WB and where the road crossing should be placed	A new footpath under consideration which would include a safe crossing	<b>PKC</b>	09 April 2013	19 January 2015
Pavement outside Shop, Kinneswood	Surface of footpath breaking up & in a poor condition	Added to the PKC list for "sealing" programme for 2015 (WClIr Robertson).	<b>PKC</b>	09 April 2013	19 January 2015