

PORTMOAK CC ROAD REPORT SUMMARY

Description	Details	Notes	With/By	First Reported	Revised
Reported to or Discussed at last Community Council Meeting & New Items Since					
Additional grass cutting	At CC meeting 8 th October it was reported that some funding had been set aside by PKC for additional cutting of roadside verges at important junctions. CC asked for recommendations.	1. Wester Balgedie / A911 junction. 2. Mawcarse / B919 junction. 3 Any other recommendations?	BC	23 Oct 2013	New
Repair to traffic island at the east end of the B9097 Ballingry junction (South Loch Road.)	Road markings badly faded making it difficult to distinguish RH slip road, curbed traffic island poorly identified.	Repaint road markings & highlight curbing on junction.	BC	23 Oct 2013	New
Traffic survey Kinnesswood	At the 8/10 CC meeting, a resident sought information on the A911 speed review & the efficacy of the build outs.	Survey has recently been undertaken – awaiting results.	PKC – ward Cllrs.	23 Oct 2013	New
Gritting & snow clearing	On-going project to improve snow clearing throughout the Portmoak CC area. PKC are to extend the use of farmers as third party contractors. CC supplied the name of 3 local farmers for consideration.	PKC made offers to 3 local farmers – no response from 2 & no commitment from any. In the absence of farmer assistance, PKC should confirm what their commitment to road clearing will be for the winter of 2013/14	PKC	9 April 2013	23 Oct 2013

PORTMOAK CC ROAD REPORT SUMMARY

Blind summit signs B9097 South Loch Road	A member of the public asked if safety on the B9097 could be improved by the reinstatement of blind summit signs, to reduce the risk of dangerous overtaking. It is anticipated but yet to be confirmed that this would be included in any carriageway improvement works.	PKC have indicated that the blind summit signs will be installed but no action as yet. Now a priority!	PKC	9 April 2013	23 Oct 2013
<i>Site lines at the new road, Kilmagadwood</i>	<i>This item is subject to ongoing discussion / dispute with PKC planning dep't.</i>		RC	9 July 2013	23 Oct 2013
Wall as you enter Kinneswood from the North West	Wall showing signs of distress and may be in danger of collapse	Repair being undertaken by landowner	PKC	28 May 2013	23 Oct 2013
Cats Eyes	Many of the existing cats eyes are "blind"	Replacement simple and inexpensive. How much are we talking about & how do we progress to action?	BC	28 May 2013	23 Oct 2013
<i>Surface painted road signage A911 Auchmuir Bridge to Milnathort</i>	<i>To reinstate the faded & missing painted road markings and non-slip surface.</i>		PKC	9 April 2013	23 Oct 2013
Improved signage Wester Balgedie A911 junction	Improvement required to the signage, road markings & additional anti-skid surfacing at the junction with the A911 from Wester Balgedie, particularly relating to the sharpness of the corner & the blind summit.	In works programme for 2013/14. No progress to date.	PKC	9 April 2013	23 Oct 2013
<i>Resurfacing B9097 South Loch Road</i>	<i>The surface on the B9097 has been causing concern for some time. It is understood that the resurfacing presently being undertaken on the west side of the motorway junction will be continued into our area, this TBC.</i>	<i>Substantial resurfacing completed over the summer months.</i> 2 notable sections yet to be completed. No confirmed programme for completion.	PKC	9 April 2013	23 Oct 2013

PORTMOAK CC ROAD REPORT SUMMARY

Replacement reflective signs New Gullet bridge B920	The yellow & black striped warning signs are missing from the parapets on either side of the bridge. These are essential safety aids.	Despite assurances from PKC no action to date. Now urgent!	PKC	9 April 2013	23 Oct 2013
On-going items					23 Oct 2013
Traffic in Wester Balgedie	Concern was raised at the size of vehicles now using the narrow road through Wester Balgedie & the associated damage.	CC to investigate.	PKC	9 April 2013	23 Oct 2013
40 MPH speed limit A911 Scotlandwell to Auchmuir Bridge	A member of the public asked if in the interest of road safety the 40MPH zone could be extended from Scotlandwell to Auchmuir Bridge. Review to be undertaken by Jillian Robinson PKC	Cllr Barnacle had previously raised this with PKC & it was felt that allowing the higher limit on the straight section permitted safer overtaking. Cllr Barnacle to ask PKC to look at this again. No action to date.	PKC	9 April 2013	23 Oct 2013
Water on the hill Wester Balgedie to Glenlomond	The on-going problem of the water flowing down the hill on the stretch between Wester Balgedie & the former water station has now been passed to PKC legal section for possible action.	Passed to PKC.	Cllr. Barnacle	9 April 2013	
Scotlandwell name sign A911	It was noted that following the change in position of the 30 mph zone entering Scotlandwell, the name sign was in the incorrect position and should be moved to the same position as the 30mph zone. In addition the long promised Britain In Bloom silver gilt (3 times winner) signs have not been installed. 3 required.	Passed to PKC.	PKC	9 April 2013	

PORTMOAK CC ROAD REPORT SUMMARY

<p>HGV traffic Portmoak</p>	<p>This project being led by Elizabeth Smith MSP to see if it is possible to reduce the use made by HGVs on the A911. CC asked to provide names of the regular haulage companies using this route.</p> <p>ES has arranged meeting with RHA</p>	<p>Liz Smith to report on meetings with national bodies. No significant progress as yet.</p>	<p>CC Calderwood MSP Smith</p>	<p>9 April 2013</p>	<p>23 Oct 2013</p>
<p>Damaged wall, Wester Balgedie</p>	<p><i>The gatepost at the entrance to the farm damaged during snow clearing activities in winter 2012/13.</i></p>	<p>No action to date.</p>	<p>PKC</p>	<p>9 April 2013</p>	<p>23 Oct 2013</p>